

SURVEYORS NOTES

USE OF THIS SURVEY FOR ANY OTHER PURPOSE OR BY OTHER PARTIES SHALL BE AT THEIR OWN RISK AND THE UNDERSIGNED SURVEYOR IS NOT RESPONSIBLE FOR ANY LOSS THEREFROM. THERE IS NO VISIBLE EVIDENCE OF AN OIL OR GAS PIPELINE ON THIS TRACT.

NO FLOOD PLAIN DESIGNATION WAS DETERMINED BY THIS SURVEYOR.

NO ATTEMPT HAS BEEN MADE TO DETERMINE OR SHOW THE EXISTENCE, LOCATION, SIZE, DEPTH, CAPACITY OR CONDITION OF ANY PROPOSED OR EXISTING UTILITIES ON THIS PROPERTY WHETHER PRIVATE, MUNICIPAL OR PUBLICLY OWNED. NO ENVIRONMENTAL OR SUBSURFACE CONDITIONS WERE SURVEYED OR EXAMINED THAT MAY AFFECT THE USE OR DEVELOPMENT OF THIS PROPERTY.


THE ADDRESS SHOWN WAS PROVIDED BY OTHERS, HARDIN SURVEYING MAKES NO CLAIM TO ITS ACCURACY.

EASEMENTS AND RESTRICTIONS ADDRESSED WERE LIMITED TO THE FOLLOWING, IN CONNECTION WITH G.F. NO.17-1447 OF COLONIAL TITLE COMPANY.

RESTRICTIONS: VOL. 595, PG. 304; VOL. 1366, PG. 502; VOL. 1348, PG. 796; DOC. • 2015-00009620; VOL. 597, PG. 598

STIPULATIONS VOL. 787, PG. 613; VOL. 885, PG. 864; VOL. 9, PG. 92; VOL. 514, PG. 463

IN MY OPINION AS A SURVEYOR (NOT A LEGAL OPINION) THE FOLLOWING DO NOT APPEAR TO AFFECT THIS TRACT: VOL. 579, PG. 92; VOL. 550, PG. 463; VOL. 550, PG. 461;



FIRM REGISTRATION NO. 10114700

I GARY L. HARDIN R.P.L.S. • 4207, DO HEREBY CERTIFY REPRESENTS THE RESULTS OF AN ON THE GROUND \$ REPRESENTS THE RESULTS OF AN ON THE GROUND S MY DIRECTION AND SUPERVISION DURING THE MONT ALL CORNERS ARE SHOWN HEREON AND THERE ARE ENCROACHMENTS, CONFLICTS OR PROTRUSIONS OTHER

GARY L. HARDÍN R.P.LS. # 4207 SIGNATURE VOID IF NOT SIGNED IN BLUE INK

© 2017 ALL RIGHTS RESERVED



PO BOX 587 MABANK, TEXAS 75147 (903) 887-5674 LOCAL (877) 329-6475 TOLL FREE (903) 887-0421 FAX

SURVEYING

DATE PERFORMED: OCTOBER 4, 2017

SCALE: 1" = 30 FEET

WORK ORDER * 1709084 DRAWN BY: JP/JH CHECKED BY: TP FIELDED BY: JT

THIS SURVEY WAS PERFORMED FOR:

STEARNS